

Monday, 22 July 2024

## Technical Bulletin (TB-2406): XP95 Base Mounted Flame Detectors

### Reason for notification:

Update to supply resumption dates for our XP95 Base Mounted Flame Detectors that contain an IR sensor.

### Detail:

As we have previously advised, our range of flame detectors had to go through an update to replace an obsolete component and as a result needed to be re-approved. Our range of base mounted flame detectors that contain an IR sensor are still going through this re-approval process, and unfortunately the scheduled testing was disrupted, delaying the expected finish date.

The products below are affected by this delay:

| Item Number  | Item Name  | Back-order supply date | Regular supply date             |
|--------------|--|------------------------|---------------------------------|
| 55000-023APO | XP95 Flame Detector (UV/IR2) - Base Mount        | February 2025          | Pending lead time from supplier |
| 55000-024APO | XP95 Flame Detector (IR3) - Base Mount           |                        |                                 |
| 55000-028MAR | XP95 Marine Flame Detector (UV/IR2) - Base Mount | H1 2025                |                                 |
| 55000-029MAR | XP95 Marine Flame Detector (IR3) - Base Mount    |                        |                                 |

### Remedy

Unfortunately, we do not have any direct replacements available for these products. We are now receiving supply of our addressable flame detectors, which may be an alternative for you. Should you wish to cancel or update your order, please contact your account manager.

### Questions

We stay at your availability for any questions or support you may need. Your account manager, as your primary contact, will be able to support you with any immediate topic and we will keep you in the close loop for any update or further information.

-END-