

Thursday 23rd May 2024

Technical Bulletin (TB-2405): Soteria UL Modules FM approvals

Reason for notification:

Change in the standard supply of Soteria UL Modules resulting in a temporary removal of the FM mark.

Detail:

Affected Part Number	Product Description
SA4705-600APO	Soteria UL Mini Switch Monitor Module
SA4705-700APO	Soteria UL Input Module
SA4705-701APO	Soteria UL Relay Output Module
SA4705-703APO	Soteria UL Switch Monitor Input/Output Module
SA4705-720APO	Soteria UL Dual Input Switch Monitor Module
SA4705-706APO	Soteria UL NAC Module

Due to a strategic factory transition, the products shown above will be supplied as standard without the FM mark until further notice. If you require the FM mark on the modules for any orders within the next six months, please inform your account manager with quantities and dates for delivery by 11th June 2024, including any orders already in the system. These orders will be subject to a lead time of approximately 12-16 weeks. When placing such orders, please indicate that the FM mark is required to avoid disappointment.

Remedy

An addendum to this bulletin will be sent once the lead time is back to normal for the module to be supplied with FM mark as standard.

Questions

Should you have any further questions, please contact your account manager.

-END-